

Service Bulletin

Nr. / no. **001-2017**

Erstellt am / made on: **01-08-2017**

Geräte/devices

<input type="checkbox"/> KD1x1	<input type="checkbox"/> KD2x2	<input type="checkbox"/> KD3x3	<input type="checkbox"/> KD3x3-F	<input type="checkbox"/> KD4x4	<input type="checkbox"/> KD4x4-F	<input type="checkbox"/> KDB/KDD
<input type="checkbox"/> HD Etronic I	<input type="checkbox"/> HD Etronic II	<input type="checkbox"/> HDE	<input type="checkbox"/> HDE-F	<input type="checkbox"/> HDB/HDD	<input type="checkbox"/> KW	
<input type="checkbox"/> KS	<input type="checkbox"/> KSM	<input type="checkbox"/> HSC	<input type="checkbox"/> MP			
<input checked="" type="checkbox"/> SmartWash	<input checked="" type="checkbox"/> SW Plus	<input checked="" type="checkbox"/> JetWash	<input checked="" type="checkbox"/> JW Plus	<input checked="" type="checkbox"/> CW Plus		
<input checked="" type="checkbox"/> CompactLine	<input checked="" type="checkbox"/> ModulLine	<input type="checkbox"/> Vacs				

Änderung der CarWash Waschplatzausrüstung HD

Aufgrund einer möglichen Verbrennungsgefahr wurde das Design der CarWash Waschplatzausrüstung geändert. Die Hochdruckpistole und das Strahlrohr sind jetzt in einer Einheit fest verbunden und mit einem Berührungsschutz versehen. Die Teile sind nicht mehr einzeln im Ersatzteil-Bereich erhältlich. Im Austauschfall muss die Hochdruckpistole und das Strahlrohr zusammen ausgetauscht werden.

Change of CarWash wash place equipment HD

Due to a possible risk of burning, the design of the CarWash wash place equipment was changed.

The high-pressure gun and the lance are now fixed in one unit and equipped with a contact protection.

The parts are no longer available individually in the spare parts area. In the case of an exchange, the high pressure gun and the jet pipe must be exchanged together.



Vorher / Before (Art.-Nr.: 394000)



Nachher / After (Art.-Nr.: 394010)

Anlage / attachment **keine / none**

geprüft am / checked on:
01-08-2017

genehmigt von / approved by:
Reiner Ehrle